

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

PUMP ASSEMBLY WITH ONE PIECE PISTON

Donald J. Shanklin et al.

Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 1



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4




Fig. 1a




Fig. 1b




Fig. 1c

PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 1d




Fig. 1e





Fig. 2



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 3






Fig. 4



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4



PUMP ASSEMBLY WITH ONE PIECE PISTON

Donald J. Shanklin et al.

Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 6




Fig. 6a

PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 7





Fig. 8



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4




Fig. 9a




Fig. 9




Fig. 10




Fig. 9b





Fig. 12
(PRIOR ART)




Fig. 13
(PRIOR ART)







Fig. 14
(PRIOR ART)



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4




PUMP ASSEMBLY WITH ONE PIECE PISTON

Donald J. Shanklin et al.

Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 17



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4




Fig. 18




Fig. 19

PUMP ASSEMBLY WITH ONE PIECE PISTON

Donald J. Shanklin et al.

Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 20





Fig. 21



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 22





Fig. 23



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 24




Fig. 25





Fig. 25a



PUMP ASSEMBLY WITH ONE PIECE PISTON
Donald J. Shanklin et al.
Appl. No.: Unknown Atty Docket: HAYESPR.1CP3C4

Fig. 26




Fig. 27

